SCREEN DEFINITIONS ScreenDefs-RevV.xls Date 7/6/2011

RED = Do NOT change.
BLANK = 0 or zero

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM		Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 65536) Ex. For a -13 Offset;Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
1	Volt Meter Input 1 Input Source 1 No alarms	140	6500	1		2.0	1	1					40		2.0								3								
2	Volt Meter Input 2 Input Source 3 No alarms	140	6500	1		2.0	1	3					40		2.0								3								
3	Volt Meter Input 3 Input Source 5 No alarms	140	6500	1		2.0	1	5					40		2.0								3								
4	Volt Meter Input 4 Input Source 7 No alarms	140	6500	1		2.0	1	7					40		2.0								3								
5	Volt Meter Input 5 Input Source 9 No alarms	140	6500	1		2.0	1	9					40		2.0								3								
6	Volt Meter Input 6 Input Source 11 No alarms	140	6500	1		2.0	1	#					40		2.0								3								

ADDRESS / ITEM
9

Volt Meter
Input 1
Input Source 1
w under/over volt alarm, 5 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
140	6500	1		2.0	1	1					40		2.0				11.000	13.000	14.500	15.000	2	3	1	3	2	1				1

ADDRESS / ITEM
10

Volt Meter
Input 1
Input Source 1
w under/over volt alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
140	6500	1		2.0	1	1					40		2.0				11.000	15.000			2	1	2			1			1	

ADDRESS / ITEM
11

Volt Meter
Input 1
Input Source 1
w over volt alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
140	6500	1		2.0	1	1					40		2.0		1		14.500	15.000			1	3	2						1	

ADDRESS / ITEM
12

Volt Meter
Input 1
Input Source 1
w under volt alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
140	6500	1		2.0	1	1					40		2.0		1		11.000	13.000			2	3	1			1				

ADDRESS / ITEM
18

Engine Temp.
Digital Meter
Input 1
Input Source 1
w under volt alarm, 2 Zone
for TMP36 Sensor
and direct in 0-5V

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	D480	1		2.0	1	1				32781	73		2.0				4.243				1	2					2			

ADDRESS / ITEM
19

Fuel Temp.
Digital Meter
Input 1
Input Source 1
w under volt alarm, 2 Zone
for TMP36 Sensor
and direct in 0-5V

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	D500	1		2.0	1	1				32781	73		2.0				2.965				2	1					1			

ADDRESS / ITEM
20

Oil Level Meter Input 1 Input Source 1 w low oil level alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	C380	13		2.0	1	1		0.000	16.383				2.0				4.000				2	1				1				

ADDRESS / ITEM
21

Oil Level Meter Input 1 Input Source 1 w low oil level alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	C380	13		2.0	1	1		0.000	16.383				2.0				3.000	4.000			2	3	1			1				

ADDRESS / ITEM
22

Fuel Gauge, Radial
Input 1
Input Source 1
w low fuel level
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	3D80	17		2.0	1	1		0.000	16.383				2.0				2.000	4.000			2	3	1			1				

ADDRESS / ITEM
23

Fuel Gauge, Radial
(Left Tank)
Input 1
Input Source 1
w low fuel level
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	8000	17		2.0	1	1		0.000	16.383				2.0				2.000	4.000			2	3	1			1				

ADDRESS / ITEM
24

Fuel Gauge, Radial
(Right Tank)
Input 1
Input Source 1
w low fuel level
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	8880	17		2.0	1	1		0.000	16.383				2.0				2.000	4.000			2	3	1			1				

ADDRESS / ITEM
25

Fuel Gauge, Radial
(Center Tank)
Input 1
Input Source 1
w low fuel level
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
1	9100	17		2.0	1	1		0.000	16.383				2.0				2.000	4.000			2	3	1			1				

ADDRESS / ITEM
26

Fuel Gauge, Radial
(Header Tank)
Input 1
Input Source 1
w low fuel level
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	9980	17		2.0	1	1		0.000	16.383				2.0				2.000	4.000			2	3	1			1				

ADDRESS / ITEM
27

Fuel Gauge, Linear
Input 1
Input Source 1
w low fuel level
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	4600	13		2.0	1	3		0.000	16.383				2.0				2.000	4.000			2	3	1			1				

ADDRESS / ITEM
28

Fuel Gauge, Linear (Left Tank) Input 1 Input Source 1 w low fuel level alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	A380	13		2.0	1	3		0.000	16.383				2.0				2.000	4.000			2	3	1			1			

ADDRESS / ITEM
29

Fuel Gauge, Linear (Right Tank) Input 1 Input Source 1 w low fuel level alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	AA00	13		2.0	1	3		0.000	16.383				2.0				2.000	4.000			2	3	1			1			

ADDRESS / ITEM
30

Fuel Gauge, Linear (Center Tank) Input 1 Input Source 1 w low fuel level alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	B080	13		2.0	1	3		0.000	16.383				2.0				2.000	4.000			2	3	1			1			

ADDRESS / ITEM
31

Fuel Gauge, Linear (Header Tank) Input 1 Input Source 1 w low fuel level alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	B700	13		2.0	1	3		0.000	16.383				2.0				2.000	4.000			2	3	1			1			

ADDRESS / ITEM
32

Amp Meter 000.0 use SHUNT 50mV=10A Input 5 Input Source 9 w over curr. alarm. 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					131		2.0		1		3.000				1	2				1			

ADDRESS / ITEM
33

Amp Meter 000.0 use SHUNT 50mV=30A Input 5 Input Source 9 w over curr. alarm. 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					43		2.0		1		3.000				1	2				1			

ADDRESS / ITEM
34
Amp Meter
000.0
use SHUNT
50mV=50A
Input 5
Input Source 9
w over curr.
alarm. 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					26		2.0		1		3.000				1	2					1		

ADDRESS / ITEM
35
Amp Meter
000.0
use SHUNT
50mV=60A
Input 5
Input Source 9
w over curr.
alarm. 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					22		2.0		1		3.000				1	2					1		

ADDRESS / ITEM
36
Amp Meter
000.0
use SHUNT
50mV=70A
Input 5
Input Source 9
w over curr.
alarm. 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					19		2.0		1		3.000				1	2					1		

ADDRESS / ITEM
37
Amp Meter
000.0
use SHUNT
50mV=80A
Input 5
Input Source 9
w over curr.
alarm. 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					16		2.0		1		3.000				1	2					1		

ADDRESS / ITEM
38
Amp Meter
000.0
use SHUNT
50mV=100A
Input 5
Input Source 9
w over curr.
alarm. 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
148	C180	1		2.0	1	9					13		2.0		1		3.000				1	2					1		

ADDRESS / ITEM
39
Amp Meter
000.
use SHUNT
50mV=100A
Input 5
Input Source 9
w over curr.
alarm. 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					131		2.0		1		3.000				1	2					1		

ADDRESS / ITEM
40
Amp Meter
000.0
use SHUNT
50mV=120A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
148	C180	1		2.0	1	9					11		2.0		1		3.000				1	2				1				

ADDRESS / ITEM
41
Amp Meter
000.
use SHUNT
50mV=120A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					108		2.0		1		3.000				1	2				1				

ADDRESS / ITEM
42
Amp Meter
000.
use SHUNT
50mV=150A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					87		2.0		1		3.000				1	2				1				

ADDRESS / ITEM
43
Amp Meter
000.
use SHUNT
50mV=180A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					73		2.0		1		3.000				1	2				1				

ADDRESS / ITEM
44
Amp Meter
000.
use SHUNT
50mV=200A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					66		2.0		1		3.000				1	2				1				

ADDRESS / ITEM
45
Amp Meter
000.
use SHUNT
50mV=300A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					44		2.0		1		3.000				1	2				1				

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM	Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
46	139	C180	1		2.0	1	9					262		2.0		1		5.900				1	2					1			
47	139	C180	1		2.0	1	9					87		2.0		1		5.900				1	2					1			
48	139	C180	1		2.0	1	9					52		2.0		1		5.900				1	2					1			
49	139	C180	1		2.0	1	9					44		2.0		1		5.900				1	2					1			
50	139	C180	1		2.0	1	9					37		2.0		1		5.900				1	2					1			
51	139	C180	1		2.0	1	9					33		2.0		1		5.900				1	2					1			

ADDRESS / ITEM 46
Amp Meter
000.0
use SHUNT
100mV=10A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

ADDRESS / ITEM 47
Amp Meter
000.0
use SHUNT
100mV=30A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

ADDRESS / ITEM 48
Amp Meter
000.0
use SHUNT
100mV=50A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

ADDRESS / ITEM 49
Amp Meter
000.0
use SHUNT
100mV=60A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

ADDRESS / ITEM 50
Amp Meter
000.0
use SHUNT
100mV=70A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

ADDRESS / ITEM 51
Amp Meter
000.0
use SHUNT
100mV=80A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

ADDRESS / ITEM
52
Amp Meter
000.0
use SHUNT
100mV=100A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
148	C180	1		2.0	1	9					26		2.0		1		5.900				1	2				1				

ADDRESS / ITEM
53
Amp Meter
000.
use SHUNT
100mV=100A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					262		2.0		1		5.900				1	2				1				

ADDRESS / ITEM
54
Amp Meter
000.0
use SHUNT
100mV=120A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
148	C180	1		2.0	1	9					22		2.0		1		5.900				1	2				1				

ADDRESS / ITEM
55
Amp Meter
000.
use SHUNT
100mV=120A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					219		2.0		1		5.900				1	2				1				

ADDRESS / ITEM
56
Amp Meter
000.
use SHUNT
100mV=150A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					175		2.0		1		5.900				1	2				1				

ADDRESS / ITEM
57
Amp Meter
000.
use SHUNT
100mV=180A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					146		2.0		1		5.900				1	2				1				

ADDRESS / ITEM
58
Amp Meter
000.
use SHUNT
100mV=200A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					131		2.0		1		5.900				1	2					1		

ADDRESS / ITEM
59
Amp Meter
000.0
use SHUNT
100mV=200A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
148	C180	1		2.0	1	9					13		2.0		1		5.900				1	2					1		

ADDRESS / ITEM
60
Amp Meter
000.
use SHUNT
100mV=300A
Input 5
Input Source 9
w over curr.
alarm, 2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					88		2.0		1		5.900				1	2					1		

ADDRESS / ITEM
61
Oil OK
High Oil Press.
Input 1
Input Source 1
w Low Press. & High Press
alarms, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	2B00	2		2.0	1	1							2.0				8.000				1	2					1		

ADDRESS / ITEM
62
Low Oil Press.
Oil OK
Input 1
Input Source 1
w Low Press. & High Press
alarms, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	2A80	2		2.0	1	1							2.0				8.000				2	1					1		

ADDRESS / ITEM
63

Low Oil Press.
Oil OK
High Oil Press.
Input 1
Input Source 1
w Low Press. & High Press
alarms, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0- 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	2A80	3		2.0	1	1							2.0				5.000	11.000			2	1	2			1		1		

ADDRESS / ITEM
64

Gear Down
Gear Up
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0- 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3700	2		2.0	1	1							2.0				8.000				1	3								

ADDRESS / ITEM
65

Gear Locked
Gear Unlocked
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0- 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	C280	2		2.0	1	1							5.0				6.000				1	3								

ADDRESS / ITEM
66

Fuel Pump Off
Fuel Pump On
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0- 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3200	2		2.0	1	1							90.0				8.000				1	2					1			

ADDRESS / ITEM
67

Low Fuel
Fuel OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0- 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	2F00	2		2.0	1	1							2.0				8.000				2	1					1			

ADDRESS / ITEM
68

<30 Min. Fuel
Fuel OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536). Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3000	2		2.0		1							2.0		1		6.000				2	1				1				

ADDRESS / ITEM
69

<45 Min. Fuel
Fuel OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536). Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3100	2		2.0		1							2.0		1		8.000				2	1				1				

ADDRESS / ITEM
70

Fuel Press. OK
High Fuel Press.
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536). Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3380	2		2.0	1	1							2.0				8.000				1	2					1			

ADDRESS / ITEM
71

Low Fuel Press.
Fuel Press. OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536). Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3300	2		2.0	1	1							2.0				8.000				2	1				1				

ADDRESS / ITEM
72

Low Fuel Press.
Fuel Press. OK
High Fuel Press
Input 1
Input Source 1
3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536). Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3300	3		2.0	1	1							2.0				5.000	11.000			2	1	3			1			1	

ADDRESS / ITEM
73

COW.FL CLOSD | COW.FL OPEN

Cowl Flaps Closed
Cowl Flaps Open
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3480	2		2.0	1	1							2.0				8.000				1	2							

ADDRESS / ITEM
74

CANPY CLOSD | CANPY OPEN

Canopy Closed
Canopy Open
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3600	2		2.0	1	1							2.0				8.000				1	2					1		

ADDRESS / ITEM
75

CKT.BR OPEN | CKT.BR CLOSD

Circcuit Breaker Open
Circuit Breaker Open
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	6F80	2		2.0	1	1							2.0				8.000				2	1				1			

ADDRESS / ITEM
76

STALL WARN | NO STALL

Stall Warning
No Stall
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3800	2		2.0	1	1							2.0				8.000				2	1				1			

ADDRESS / ITEM
77

FLAPS DOWN | FLAPS UP

Flaps Down
Flaps Up
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3900	2		2.0	1	1							2.0				8.000				2	1				1			

ADDRESS / ITEM
78

FLAPS OK | FLAPS SPEED

Flaps OK
Flaps Overspeed
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3A00	2		2.0	1	1							2.0				8.000				1	2				1			

ADDRESS / ITEM
79

Vacuum OK
High Vacuum
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3C80	2		2.0	1	1							2.0				8.000				1	2				1				

ADDRESS / ITEM
80

Low Vacuum
Vacuum OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3C00	2		2.0	1	1							2.0				8.000				2	1				1				

ADDRESS / ITEM
81

Low Vacuum
Vacuum OK
High Vacuum
Input 1
Input Source 1
3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3C00	3		2.0	1	1							2.0				5.000	11.000			2	1	3			1				

ADDRESS / ITEM
82

Low Voltage
Voltage OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	6C80	2		2.0	1	1							2.0				12.000				2	1				1				

ADDRESS / ITEM
83

Low Voltage
Voltage OK
High Voltage
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	6C80	3		2.0	1	1							2.0				11.000	14.500			3	1	2		0	1		1		

ADDRESS / ITEM
84

Voltage OK
High Voltage
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	6D00	2		2.0	1	1							2.0				14.500				1	2					1			

ADDRESS / ITEM
85

Low Current
Current OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	6E00	2		2.0	1	1							2.0				8.000				2	1				1				

ADDRESS / ITEM
86

Low Current
Current OK
High Current
Input 1
Input Source 1
3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	6E00	3		2.0	1	1							2.0				5.000	11.000			3	1	2			1		1		

ADDRESS / ITEM
87

Current OK
High Current
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	6E80	2		2.0	1	1							2.0				8.000				1	2					1			

CARB. ICE | CARB. T. OK

ADDRESS / ITEM
88

Carb. Ice
Carb. Temp OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7080	2		2.0	1	1							2.0				8.000				2	1				1				

CARB. ICE | CARB. T. OK | CARB. TMP. HI

ADDRESS / ITEM
89

Carb. Ice
Carb. Temp OK
High Carb. Temp
Input 1
Input Source 1
3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7080	3		2.0	1	1							2.0				5.000	11.000			2	1	3			1		1		

CARB. T. OK | CARB. TMP. HI

ADDRESS / ITEM
90

Carb. Temp OK
High Carb. Temp
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7100	2		2.0	1	1							2.0				8.000				1	2					1			

EGT OK | HIGH EGT

ADDRESS / ITEM
91

Exhaust Gas Temp OK
Exhaust Gas Temp
High
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7300	2		2.0	1	1							2.0				8.000				1	2					1			

CABIN FIRE | NO FIRE

ADDRESS / ITEM
92

Cabin Fire
No Fire
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7400	2		2.0	1	1	1						2.0				8.000				1	2					1			

ADDRESS / ITEM
93

No Fire
Engine Fire
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7480	2		2.0	1	1							2.0				8.000				1	2					1		

ADDRESS / ITEM
94

Low Manif. Press.
Manifold Press. OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7580	2		2.0	1	1							2.0				8.000				2	1					1		

ADDRESS / ITEM
95

Low Manif. Press.
Manifold Press. OK
High Manif. Press.
Input 1
Input Source 1
3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7580	3		2.0	1	1							2.0				5.000	11.000			2	1	3				1		

ADDRESS / ITEM
96

Manifold Press. OK
High Manif. Press.
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7600	2		2.0	1	1							2.0				8.000				1	2					1		

ADDRESS / ITEM
97

Starter OK
Starter On
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7900	2		2.0	1	1							90.0				8.000				1	2					1		

ADDRESS / ITEM
98

RPM OK
High RPM
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7C00	2		2.0	1	1							2.0				8.000				1	2				1				

ADDRESS / ITEM
99

RPM OK
Bad RPM
RPM OK
Input 1
Input Source 1
3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7A00	3		2.0	1	1							2.0				5.000	11.000			1	2	1			1		1		

ADDRESS / ITEM
100

LowRPM
RPM OK
High RPM
Input 1
Input Source 1
3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7B80	3		2.0	1	1							2.0				5.000	11.000			3	1	2							

ADDRESS / ITEM
101

Speed OK
High Speed
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7F00	2		2.0	1	1							2.0				8.000				1	2				1				

ADDRESS / ITEM
102

Low Speed
Speed OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7E80	2		2.0	1	1							2.0				8.000				2	1				1				

ADDRESS / ITEM
103

Low Speed
Speed OK
High Speed
Input 1
Input Source 1
3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7E80	3		2.0	1	1							2.0				5.000	11.000			2	1	3			1		1		

ADDRESS / ITEM
104

Low Oil Temp.
Oil Temp OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	A200	2		2.0	1	1							2.0				8.000				3	1				1				

ADDRESS / ITEM
105

Low Oil Temp.
Oil Temp OK
High Oil Temp
Input 1
Input Source 1
3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset:Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	A200	3		2.0	1	1							2.0				5.000	10.000			3	1	2			1		1		

ADDRESS / ITEM
106

Oil Temp OK
High Oil Temp
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	A280	2		2.0	1	1							2.0				8.000				1	2					1			

ADDRESS / ITEM
107

Low Oxygen Flow
Oxygen Flow OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	BE80	2		2.0	1	1							2.0				8.000				2	1					1			

ADDRESS / ITEM
108

Low Oxygen Press
Oxygen Press OK
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7800	2		2.0	1	1							2.0				8.000				2	1					1			

ADDRESS / ITEM
109

Low Altitude
Altitude OK
High Altitude
Input 1
Input Source 1
3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7D00	3		2.0	1	1							2.0				5.000	11.000			2	1	3				1			

ADDRESS / ITEM
110

Altitude OK
High Altitude
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7D80	3		2.0	1	1							2.0				5.000				1	2					1			

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM
111

LOW ALTI. | ALTI. OK

Low Altitude
Altitude OK
Input 1
Input Source 1
2 Zone

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7D00	3		2.0	1	1							2.0				5.000				2	1				1				

ADDRESS / ITEM
112

OAT ICE | OAT OK

OAT Ice Warning
OAT OK
Input 1
Input Source 1
2 Zone

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7700	2		2.0	1	1							2.0				8.000				2	1				1				

ADDRESS / ITEM
113

NO CO | CO WARN

NO CO
CO Warning
Input 1
Input Source 1
2 Zone

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	3B00	2		2.0	1	1							2.0				8.000				1	2					1			

ADDRESS / ITEM
114

TIRE PRESS | TIRE PRS.OK

Low Tire Press.
Tire Press. OK
Input 1
Input Source 1
2 Zone

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	BD80	2		2.0	1	1							2.0				8.000				2	1				1				

ADDRESS / ITEM
115

DOOR CLOSD | DOOR OPEN

Door Closed
Door Open
Input 1
Input Source 1
2 Zone

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	2D00	2		2.0	1	1							2.0				8.000				1	2				1				

ADDRESS / ITEM
116

BAG.DR CLOSD | BAG.DR OPEN

Bagg. Door Closed
Bagg. Door Open
Input 1
Input Source 1
2 Zone

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	2E00	2		2.0	1	1							2.0				8.000				1	2				1				

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM		Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
117	Oil Door Closed Oil Door Open Input 1 Input Source 1 2 Zone	32	2C00	2		2.0	1	1							2.0				8.000				1	2				1			
118	Low Oil Level Oil Level OK Input 1 Input Source 1 2 Zone	32	2880	2		2.0	1	1							5.0				3.500				2	1				1			
119	Cyl. Head Temp OK High Cyl. Head Temp Input 1 Input Source 1 3 Zone	32	CA80	2		2.0	1	1							2.0				8.000				1	2				1			
120	ALT., ALT. OK Input 1 Input Source 1 2 Zone	32	CB80	2		2.0	1	1							3.0				11.000				2	1				1			
121	EFIS Alarm EFIS OK Input 1 Input Source 1 2 Zone	32	CC80	2		2.0	1	1							3.0				6.000				2	1				1			
122	EIS Alarm EIS OK Input 1 Input Source 1 2 Zone	32	CD00	2		2.0	1	1							3.0				6.000				2	1				1			

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM		Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset;Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
123	GEARBX CHP / GEARBOX OK	32	CE80	2		2.0	1	1							3.0				11.000				2	1				1			
124	GEARBX TMP / GEARBOX OK	32	CF00	2		2.0	1	1							3.0				6.000				1	2				1			
125	LOW COLNT / COLNT OK	32	D000	2		2.0	1	1							3.0				6.000				2	1				1			
126	LOW FUEL / FUEL OK	32	2F00	2		2.0	1	1							2.0				8.000				2	1				1			
127	LOW FUEL / FUEL OK	32	2F00	2		2.0	1	1							2.0				8.000				2	1				1			
128	CANPY LOCKD / CANPY OPEN	32	D300	2		2.0	1	1	1						2.0				8.000				2	1				1			

Gearbox Chip Detect
Gearbox OK
Input 1
Input Source 1
2 Zone

Gearbox Over Temp.
Gearbox OK
Input 1
Input Source 1
2 Zone

Low Coolant Level
Coolant OK
Input 1
Input Source 1
2 Zone

Low Fuel Left
Fuel OK
Input 1
Input Source 1
2 Zone

Low Fuel Right
Fuel OK
Input 1
Input Source 1
2 Zone

Canopy Locked
Canopy Open
Input 1
Input Source 1
2 Zone

ADDRESS / ITEM
129

Canopy Locked
Canopy Open
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	2980	2		2.0	1	1							2.0				8.000				2	1					1		

ADDRESS / ITEM
132

Amp Meter
000.0
use SHUNT
50mV=10A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					131		2.0		1		2.600	3.000			1	3	2				1		

ADDRESS / ITEM
133

Amp Meter
000.0
use SHUNT
50mV=30A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					43		2.0		1		2.600	3.000			1	3	2				1		

ADDRESS / ITEM
134

Amp Meter
000.0
use SHUNT
50mV=50A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					26		2.0		1		2.600	3.000			1	3	2				1		

ADDRESS / ITEM
135

Amp Meter
000.0
use SHUNT
50mV=60A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					22		2.0		1		2.600	3.000			1	3	2				1		

ADDRESS / ITEM
136

Amp Meter
000.0
use SHUNT
50mV=70A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					19		2.0		1		2.600	3.000			1	3	2				1		

ADDRESS / ITEM
137
Amp Meter
000.0
use SHUNT
50mV=80A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					16		2.0		1		2.600	3.000			1	3	2					1	

ADDRESS / ITEM
138
Amp Meter
000.0
use SHUNT
50mV=100A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
148	C180	1		2.0	1	9					13		2.0		1		2.600	3.000			1	3	2					1	

ADDRESS / ITEM
139
Amp Meter
000.
use SHUNT
50mV=100A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					131		2.0		1		2.600	3.000			1	3	2					1	

ADDRESS / ITEM
140
Amp Meter
000.0
use SHUNT
50mV=120A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
148	C180	1		2.0	1	9					11		2.0		1		2.600	3.000			1	3	2					1	

ADDRESS / ITEM
141
Amp Meter
000.
use SHUNT
50mV=120A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					108		2.0		1		2.600	3.000			1	3	2					1	

ADDRESS / ITEM
142
Amp Meter
000.
use SHUNT
50mV=150A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					87		2.0		1		2.600	3.000			1	3	2					1	

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM	Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
143	147	C100	1		2.0	1	9					73		2.0		1		2.600	3.000			1	3	2				1		
144	147	C100	1		2.0	1	9					66		2.0		1		2.600	3.000			1	3	2				1		
145	147	C100	1		2.0	1	9					44		2.0		1		2.600	3.000			1	3	2				1		
146	139	C180	1		2.0	1	9					262		2.0		1		5.200	5.900			1	3	2				1		
147	139	C180	1		2.0	1	9					87		2.0		1		5.200	5.900			1	3	2				1		
148	139	C180	1		2.0	1	9					52		2.0		1		5.200	5.900			1	3	2				1		

ADDRESS / ITEM	
143	AMPS Amp Meter 000. use SHUNT 50mV=180A Input 5 Input Source 9 w over curr. alarm, 3 Zone
144	AMPS Amp Meter 000. use SHUNT 50mV=200A Input 5 Input Source 9 w over curr. alarm, 3 Zone
145	AMPS Amp Meter 000. use SHUNT 50mV=300A Input 5 Input Source 9 w over curr. alarm, 3 Zone
146	AMPS. Amp Meter 000.0 use SHUNT 100mV=10A Input 5 Input Source 9 w over curr. alarm, 3 Zone
147	AMPS. Amp Meter 000.0 use SHUNT 100mV=30A Input 5 Input Source 9 w over curr. alarm, 3 Zone
148	AMPS. Amp Meter 000.0 use SHUNT 100mV=50A Input 5 Input Source 9 w over curr. alarm, 3 Zone

ADDRESS / ITEM
149
Amp Meter
000.0
use SHUNT
100mV=60A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					44		2.0		1		5.200	5.900			1	3	2					1	

ADDRESS / ITEM
150
Amp Meter
000.0
use SHUNT
100mV=70A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					37		2.0		1		5.200	5.900			1	3	2					1	

ADDRESS / ITEM
151
Amp Meter
000.0
use SHUNT
100mV=80A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C180	1		2.0	1	9					33		2.0		1		5.200	5.900			1	3	2					1	

ADDRESS / ITEM
152
Amp Meter
000.0
use SHUNT
100mV=100A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
148	C180	1		2.0	1	9					26		2.0		1		5.200	5.900			1	3	2					1	

ADDRESS / ITEM
153
Amp Meter
000.
use SHUNT
100mV=100A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					262		2.0		1		5.200	5.900			1	3	2					1	

ADDRESS / ITEM
154
Amp Meter
000.0
use SHUNT
100mV=120A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
148	C180	1		2.0	1	9					22		2.0		1		5.200	5.900			1	3	2					1	

AMPS

ADDRESS / ITEM
155
Amp Meter
000.
use SHUNT
100mV=120A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					219		2.0		1		5.200	5.900			1	3	2					1	

AMPS

ADDRESS / ITEM
156
Amp Meter
000.
use SHUNT
100mV=150A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					175		2.0		1		5.200	5.900			1	3	2					1	

AMPS

ADDRESS / ITEM
157
Amp Meter
000.
use SHUNT
100mV=180A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					146		2.0		1		5.200	5.900			1	3	2					1	

AMPS

ADDRESS / ITEM
158
Amp Meter
000.
use SHUNT
100mV=200A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					131		2.0		1		5.200	5.900			1	3	2					1	

AMPS
.

ADDRESS / ITEM
159
Amp Meter
000.0
use SHUNT
100mV=200A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
148	C180	1		2.0	1	9					13		2.0		1		5.200	5.900			1	3	2					1	

AMPS

ADDRESS / ITEM
160
Amp Meter
000.
use SHUNT
100mV=300A
Input 5
Input Source 9
w over curr.
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	C100	1		2.0	1	9					88		2.0		1		5.200	5.900			1	3	2					1	

ADDRESS / ITEM
161

Fuel Press.
Dig. Meter
1DP
Input 1
Input Source 1

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	C100	1		2.0	1	1				32811	140		2.0		1		2.213	3.613			1					1				

ADDRESS / ITEM
162

Carb. Temp
Dig. Meter
0DP
Input 1
Input Source 1

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
131	D600	1		2.0	1	1				0	20		2.0		1		2.000	4.000			2	3	1			1				

ADDRESS / ITEM
163

Landing Brake
(5 Screens)
Input 1
Input Source 1

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	D680	5		2.0	1	1		0.000	16.383				2.0		1		2.000	4.000	6.000	8.000	3	3	3	3	1					

ADDRESS / ITEM
164

Oil Press.
Dig. Meter
1DP
Input 1
Input Source 1

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	D900	1		2.0	1	1				0	64		2.0		1		1.000	2.000			2	3	1			1				

ADDRESS / ITEM
165

Oil Temp.
Dig. Meter
0DP
Input 1
Input Source 1

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	D980	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1		

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM		Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
166	CHT 1 Dig. Meter 0DP Input 1 Input Source 1	147	DA00	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM		Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
167	CHT 2 Dig. Meter 0DP Input 1 Input Source 1	147	DA80	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM		Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
168	CHT 3 Dig. Meter 0DP Input 1 Input Source 1	147	DB00	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM		Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
169	CHT 4 Dig. Meter 0DP Input 1 Input Source 1	147	DB80	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM		Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
170	CHT 5 Dig. Meter 0DP Input 1 Input Source 1	147	DC00	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM		Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
171	CHT 6 Dig. Meter 0DP Input 1 Input Source 1	147	DC80	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM		Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
172	EGT 1 Dig. Meter 0DP Input 1 Input Source 1	147	DD00	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	
173	EGT 2 Dig. Meter 0DP Input 1 Input Source 1	147	DD80	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	
174	EGT 3 Dig. Meter 0DP Input 1 Input Source 1	147	DE00	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	
175	EGT 4 Dig. Meter 0DP Input 1 Input Source 1	147	DE80	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	
176	EGT 5 Dig. Meter 0DP Input 1 Input Source 1	147	DD00	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	
177	EGT 6 Dig. Meter 0DP Input 1 Input Source 1	147	DF80	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	

G=1, R=2, Y=3, NONE=0

ADDRESS / ITEM	Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
178	147	E000	1		2.0	1	1				0	64		2.0		1		1.000	2.000			2	3	1			1			
179	147	E080	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	
180	147	E100	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	
181	139	E180	1		2.0	1	1				0	64		2.0		1		1.000	2.000			2	3	1			1			
182	139	E200	1		2.0	1	1				0	64		2.0		1		1.000	2.000			2	3	1			1			
183	147	E280	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	

ADDRESS / ITEM 178

Tire Press.
Dig. Meter
0DP
Input 1
Input Source 1

TIRE P.

ADDRESS / ITEM 179

RPM
Dig. Meter
0DP
Input 1
Input Source 1

RPM

ADDRESS / ITEM 180

Air Speed
Dig. Meter
0DP
Input 1
Input Source 1

AIR SP.

ADDRESS / ITEM 181

Suction
Dig. Meter
1DP
Input 1
Input Source 1

SUCTN
.

ADDRESS / ITEM 182

Manif. Press.
Dig. Meter
1DP
Input 1
Input Source 1

MAN P.
.

ADDRESS / ITEM 183

Coolent Temp.
Dig. Meter
0DP
Input 1
Input Source 1

COLNT
F°

ADDRESS / ITEM
184

Water Temp.
Dig. Meter
0DP
Input 1
Input Source 1

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536). Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	E300	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2					1	

ADDRESS / ITEM
185

Altitude.
Dig. Meter
0DP
Input 1
Input Source 1

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536). Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	E380	1		2.0	1	1				0	64		2.0		1		1.000	2.000			2	3	1			1				

ADDRESS / ITEM
186

Altitude.
Dig. Meter
0DP
Input 1
Input Source 1

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536). Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	E400	1		2.0	1	1				0	64		2.0		1		1.000	2.000			2	3	1			1				

ADDRESS / ITEM
187

G Meter
Dig. Meter
1DP
Input 1
Input Source 1

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536). Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
139	E480	1		2.0	1	1				0	64		2.0		1		1.000	2.000			1	3	2			1				

ADDRESS / ITEM
188

OAT
Dig. Meter
0DP
Input 1
Input Source 1

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0 - 65536). Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
147	E500	1		2.0	1	1				0	64		2.0		1		1.000	2.000			2	3	1	1	3	2	1			1

ADDRESS / ITEM
249

AG6 ON

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	7200	2		1.0	1	1							2.0		1		8.000				1	1								

ADDRESS / ITEM
250

Oil Door Closed
Oil Door Open
Input 1
Input Source 1
2 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
32	2C00	2		2.0	1	1		0.000	16.383				2.0				8.000				1	2					1			

ADDRESS / ITEM
251

Fuel Gauge, Radial
(Left Tank)
Input 1
Input Source 1
w low fuel level
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	8000	17		2.0	1	1		0.000	16.383				2.0				2.000	4.000			2	3	1				1			

ADDRESS / ITEM
252

Fuel Gauge, Radial
(Right Tank)
Input 1
Input Source 1
w low fuel level
alarm, 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
64	8880	17		2.0	1	1		0.000	16.383				2.0				2.000	4.000			2	3	1				1			

ADDRESS / ITEM
253

Volt Meter
Input 1
Input Source 1
w under/over volt
alarm, 5 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
140	6500	1		2.0	1	1					40		2.0		1		11.000	13.000	14.500	15.000	2	3	1	3	2	1				1

ADDRESS / ITEM
254

Amp Meter
000.0
use SHUNT
100mV=100A
Input 5
Input Source 9
w over curr.
alarm. 3 Zone

G=1, R=2, Y=3, NONE=0

Screen Type (1, 2, 8)	Screen Base Address	Frames (1 - 32)	Overlay Base Address	Screen Dwell Time (Seconds 0 to 25.5)	Visible during Scan?	Input Source (1 to 12)	Invert Screen Frames Inverted? (0-1)	Calibration Minimum (Volts, 16.383 max.)	Calibration Maximum (Volts, 16.383 max.)	Offset (Dig. Meter) (range 0-65536) Ex. For a -13 Offset,Offset = 13 + 32768	Gain (0 to 65535)	Table Base Address (not used yet)	Alarm Dwell Time (0 to 409.0 Sec. Max)	Alarm Masked?	Self Reset?	Overlay Present During Alarm? (0 - 1)	Zone 1 Boundary (Volts, 16.383 max.)	Zone 2 Boundary (Volts, 16.383 max.)	Zone 3 Boundary (Volts, 16.383 max.)	Zone 4 Boundary (Volts, 16.383 max.)	Zone 1 Color	Zone 2 Color	Zone 3 Color	Zone 4 Color	Zone 5 Color	Zone 1 Alarm Enable	Zone 2 Alarm Enable	Zone 3 Alarm Enable	Zone 4 Alarm Enable	Zone 5 Alarm Enable
148	C180	1		2.0	1	9					26		2.0		1		5.200	5.900			1	3	2					1		