

Kit Contents Report

KIT PN	Spark Plug Size	LMAG	RMAG	Comp. HARNESS	CLAMP KIT	GASKET	STUD(S)	ADAPTER(S)	AUTOLITE SPARK PLUG	Notes
K4315	3/4	4371	4370	M2508	M3784	2ea. M3426	N/A	N/A	-37, -38, -38S, -40	2
K4316	3/4	4372	4370	M2508	M3784	2ea. M3426	N/A	N/A	-37, -38, -38S, -40	2
K4317	3/4	4373	4370	M2508	M3784	2ea. M3426	N/A	N/A	-37, -38, -38S, -40	2, 3
K4325	3/4	4371	4371	M2508	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-37, -38, -38S, -40	2
K4326	3/4	4373	4373	M2508	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-36S, -37, -38, -38S, -40	2, 3
K4334	5/8	4333	4333	M2045	M3784	2ea. M3411	N/A	N/A	-37BY, -38, -38S, -40	4
K4392	3/4	4392	4392	M4049	M3784	2ea. M3411	N/A	N/A	-32, -32S	
K4516	5/8	4371	4370	M4001	M3784	2ea. M3426	N/A	N/A	-36S, -37, -37BY, -38, -38S, -40	2
K4517	5/8	4373	4370	M4004	M3784	2ea. M3426	N/A	N/A	-36S, -37, -37BY, -38, -38S, -40	2
K4518	5/8	4373	4370	M4005	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S, -40	2
K4520	5/8	4301	4301	M1780	M3328	2ea. M3411	N/A	N/A	-37BY, -38, -38S, -40	5
K4522	5/8	4302	4302	M2045	M3784	2ea. M3411	N/A	N/A	-37BY, -38, -38S, -40	
K4525	5/8	4371	4371	M4001	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-36S, -37, -37BY, -38, -38S, -40	2
K4526	5/8	4330	4330	M4000	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-37, -37BY, -38, -38S, -40	2
K4527	5/8	4371	4371	M4002	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-37BY, -38, -38S, -40	2, 3
K4528	5/8	4373	4373	M4004	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-36S, -37, -37BY, -38, -38S, -40	2, 3
K4529	5/8	4381	4381	M4001	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S, -40	2
K4530	5/8	4372	4370	M4004	M3784	2ea. M3426	N/A	N/A	-37, -37BY, -38, -38S, -40	2
K4532	5/8	4372	4372	M4004	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-37, -37BY, -38, -38S, -40	2, 3
K4534	5/8	4372	4372	M4001	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-37BY, -38, -38S, -40	2
K4535	5/8	4345	4370	M4012	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S	1, 2, 3
K4536	5/8	4347	4370	M4004	M3784	2ea. M3426	N/A	N/A	-37, -37BY, -38, -38S, -40	2
K4537	5/8	4381	4370	M4001	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S, -40	2
K4539	5/8	4347	4370	M4007	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S, -40	2
K4540	5/8	4373	4354	M4000	M3784	2ea. M3426	N/A	N/A	-36S, -37, -38S, -40	2
K4541	5/8	4347	4370	M4014	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S, -40	2, 3
K4542	5/8	4373	4353	M4005	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S, -40	2, 3
K4543	5/8	4347	4342	M4004	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S, -40	2, 3
K4545	5/8	4345	4345	M4007	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S	1, 2, 3
K4547	5/8	4372	4372	M4027	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-37BY, -38, -38S	2, 3
K4548	3/4	4372	4372	M4029	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-37, -38, -38S, -40	2, 3
K4549	3/4	4372	4370	M4029	M3784	2ea. M3426	N/A	N/A	-37, -38, -38S, -40	2, 3
K4565	5/8	4372	4370	M4001	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S, -40	2
K4566	5/8	4372	4370	M4027	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S	2, 3
K4567	5/8	4373	4370	M4006	M3784	2ea. M3426	N/A	N/A	-36S, -37, -37BY, -38, -38S, -40	2, 3
K4568	5/8	4373	4370	M4027	M3784	2ea. M3426	N/A	N/A	-37BY, -38, -38S	2, 3
K4575	5/8	4373	4373	M4000	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-36S, -37, -37BY, -38, -38S, -40	2
K4576	5/8	4373	4373	M4005	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-37BY, -38, -38S, -40	2, 3
K4577	5/8	4373	4373	M4006	M3784	1ea. M3410; 2ea. M3426	2ea. M3413 Mounting Stud	1ea. M2638-4	-36S, -37, -37BY, -38, -38S, -40	2, 3
K6313	3/4	6309	6313	M2381	M3328	2ea. M3411	N/A	N/A	-32, -38, -38S, -40	
K6316	3/4	6351	6350	M2899	M3784	2ea. M3426	N/A	N/A	-32, -32S, -36S, -37, -38, -38S, -40	
K6317	3/4	6355	6350	M2896	M3784	2ea. M3426	N/A	N/A	-38, -38S, -40	
K6320	3/4	6310	6310	M2381	M3328	2ea. M3411	N/A	N/A	-32, -32S, -36S, -38, -38S, -40	
K6321	3/4	6320	6320	M2780	M3328	2ea. M3411	N/A	N/A	-32, -32S, -36S	
K6322	3/4	6314	6314	M2778	M3328	2ea. M3411	N/A	N/A	-38, -38S, -40	7
K6323	3/4	6324	6324	M2778	M3328	2ea. M3411	N/A	N/A	-38, -38S	
K6325	3/4	6355	6355	M2896	M3784	2ea. M3426	N/A	N/A	-38, -38S, -40	
K6326	5/8	6367	6367	M2938	M3520	2ea. M3411	N/A	N/A	-37BY, -38, -38S, -40	
K6327	5/8	6364	6364	M2932	M3520	2ea. M3411	N/A	N/A	-37BY, -38, -38S, -40	
K6328	3/4	6320	6320	M2779	M3328	2ea. M3411	N/A	N/A	-32, -32S, -36S	
K6377	3/4	6377	6377	M6071	M3328	2ea. M3411	N/A	N/A	-38, -38S, -40	8
K6379	3/4	6379	6379	M6071	M3328	2ea. M3411	N/A	N/A	-38, -38S, -40	8
K6513	5/8	6309	6313	M2828	M3328	2ea. M3411	N/A	N/A	-38, -38S, -40	
K6516	5/8	6351	6350	M2883	M3784	2ea. M3426	N/A	N/A	-38, -38S, -40	
K6518	5/8	6351	6350	M6001	M3784	2ea. M3426	N/A	N/A	-36S, -38, -38S, -40	
K6519	5/8	6351	6350	M6000	M3784	2ea. M3426	N/A	N/A	-36S, -38, -38S, -40	
K6520	5/8	6310	6310	M2828	M3328	2ea. M3411	N/A	N/A	-38, -38S, -40	
K6526	5/8	6355	6355	M6002	M3784	2ea. M3426	N/A	N/A	-38, -38S, -40	
K6535	5/8	6393	6350	M6002	M3784	2ea. M3426	N/A	N/A	-36S, -37, -38, -38S, -40	
K6536	5/8	6393	6350	M6014	M3784	2ea. M3426	N/A	N/A	-36S, -37, -38, -38S, -40	
K6565	5/8	6355	6350	M6002	M3784	2ea. M3426	N/A	N/A	-38, -38S, -40	
K6566	5/8	6355	6350	M6004	M3784	2ea. M3426	N/A	N/A	-38, -38S, -40	
K6577	5/8	6377	6377	M6068	M3328	2ea. M3411	N/A	N/A	-37BY, -38, -38S, -40	8
K6579	5/8	6379	6379	M6068	M3328	2ea. M3411	N/A	N/A	-37BY, -38, -38S, -40	8